



FASTER Eh & REALLY FAST Eh?

Technical Bulletin

APPLICATION

ALWAYS MAKE A TEST FIRST...!!!

Faster, Eh? is a new FuseFX part "A" (Eh?) platinum silicone developed to speed up the curing time of all FuseFX silicone paints. Use instead of regular part "A". Faster-Eh? will give your FuseFX silicone paints a working time of 5 to 7 minutes and a cure time of 30 to 40 minutes.



Faster-Eh? can be slowed down by adding solvents to the mix. For airbrushing, a working time of 20 minutes can be achieved by mixing 1.5 to 2 parts solvent to 1 part of mixed FuseFX paint.

REALLY Fast-Eh? is a new and even faster platinum silicone FuseFX part "A" (Eh?). Use instead of regular part "A". REALLY Fast-Eh? will give your FuseFX silicone paints a working time of 2 to 3 minutes and a curing time of 8 to 10 minutes.

This is especially useful when patient/model are wearing the prosthesis or prosthetic and touch ups are required. Adding a final micro thin coat of FuseFX Liquid Sheen will render the surface semi-matt without heavy powdering, bringing the shine down to a natural sheen.

Really Fast-Eh? for airbrushing.

A working time of 20 minutes can be achieved by mixing 1.5 to 2 parts solvent to 1 part of mixed FuseFX paint.

